PONDICHERRY UNIVERSITY ENGINEERING WING

Name of Work: Maintenanace of E-11 Quarters to arrest the Leakage, painting works and D-23 maintenance works for replacement of the doors

Schedule of work

S.No	Description Description	Qty	Rate	Unit	Amount
1	Code no:15.23.1				
	Dismantling tile work in floors and roofs laid in cement mortar including stacking material within 50m lead - For thickness of tiles above 10mm and upto 25mm.	155.00		Sqm	
2	Code no:12.20				
	Providing and laying pressed clay tiles (as per approved pattern 18mm nominal thickness and of approved size) on roofs jointed with cement mortar 1:4 (1 cement: 4 coarse sand) mixed with 2% intergral water proofing compound laid over a bed of 20mm thick cement mortar 1:4 (1 cement: 4 coarse sand) and finished neat complete.	155.00		Sqm	
3	Code no:15.56				
4	Dismantling old plaster or skirting raking out joints and cleaning the surface for plaster including disposal of rubbish to the dumping ground within 50m lead. Code no:13.3.1	70.00		Sqm	
_	20mm cement plaster of mix 1:4 (1cement : 4 fine sand)	70.00		Sqm	
5	Code no:13.47.1				
6	Finishing walls with Premium Acrylic Smooth exterior paint with Silicone additives of required shade - New work (Two or more coats applied @ 1.43 ltr / 10 sqm over and including base coat of water proofing cement paint applied @ 2.20 kg/10 sqm). Code no:14.67.2			Sqm	
—	Finishing walls with Premium Acrylic Smooth	580.00		Sqm	
	exterior paint with Silicone additives of required shade - Old work (one or more coats applied @ 0.83 ltr/10 sqm)	300.00		Oqiii	
7	Code no:14.45.1				
	Distempering with oil bound washable distemper of approved brand and manufacture to give an even shade - Old work (one or more coats).	290.00		Sqm	

8	Code no:14.54.1			
	Painting with synthetic enamel paint of	230.00	Sqm	
	approved brand and manufacture of required			
	colour to give an even shade - One or more			
	coats on old work.			
9	Code no:14.42.2			
	White washing with lime to give an even	270.00	Sqm	
	shade - Old work (one or more coats).			
10	Code no:9.21.1			
	Providing and fixing ISI marked flush door	2.00	Sqm	
	shutters conforming to IS:2202 (Part 1) non-			
	decorative type, core of block board			
	construction with frame of 1 st class hard			
	wood and well matched commercial 3 ply			
	veneering with vertical grains or cross bands			
	and face veneers on both faces of			
	shutters 35 mm thick including ISI marked			
	stainless steel butt hinges with necessary			
	screws			
11	Code no:9.9.1.2V	4.00		
	Providing and fixing glazed shutters for	1.00	sqm	
	doors, windows and clerestory windows			
	using 4mm thick float glass panes including			
	black enamelled ISI marked MS butt hinges			
	with necessary screws Vengai wood -			
12	30mm thick Code no:9.97.2			
12	Providing and fixing aluminium tower bolts	4.00	Each	
	ISI marked anodised (anodic coating not less	4.00	Each	
	than grade AC 10 as per IS:1868)			
	transparent or dyed to required colour or			
	shade with necessary screws etc.complete :-			
	250x10mm			
13	Code no:9.100.1			
	Providing and fixing aluminium handles ISI	4.00	Each	
	marked anodised (anodic coating not less			
	than grade AC 10 as per IS:1868)			
	transparent or dyed to required colour or			
	shade with necessary screws etc.complete :-			
	125mm			
14	Code no:13.50.1			
	Applying priming coat - with ready mixed	6.00	 Sqm	
	pink or grey primer of approved brand and			
	manufacture on wood work (hard and soft			
	wood).			

15	Code no:13.61.1			
	Painting with synthetic enamel paint of	6.00	Sqm	
	approved brand and manufacture to give an			
	even shade - Two or more coats on new			
	work.			
16	Code no:12.20L			
	Lime concrete terracing on roofs of required	3.00	Cum	
	thickness laid to fall with 25mm nominal size			
	brick aggregate and 50% lime mortar 1:2 (1			
	lime putty : 2 surkhi) rammed and finished			
	with gur and belgiri treatment complete			
	including rounding of junctions with parapet wall complete			
17	Code no:MR		+ +	
	Supply and Apply of Dr.Fixit Heavy duty,	86.00	Sqm	
	reinforced acrylic coating, new coat for open	00.00		
	terrace.			
18	Code no:MR			
	Clean the surface, supply and apply of quick	1.00	Job	
	setting chemicals and Polysulphide sealent			
	in the floor trap area, so as to complete seal			
	the water leakage in the RCC slab.			
	(Ref:Work Order No:PU/AE/W.O/2009-			
	10/8351 dt:14.05.10)			
19	Code no:MR			
	Supplying water proofing compound for	15.00	Kg	
	mixing cement mortar as per the			
	manufacturers recomentatin as decided by			
	the Engineer-in-Charge			
20	Code no:MR	40.00	0	
	Extra lead to dispose the dismatled and	10.00	Cum	
	demolished materials to a far away distance			
	as directed by Engineer-in-Charge			
			Total	
I hearby abide by the rules and regulation stipulated in the CPWD form no 6 & 8				

Contractor

Assistant Engineer