PONDICHERRY UNIVERSITY ENGINEERING WING

SCHEDULE OF WORK

Name of the work: Annual maintenance and special repairs to the Health Centre at University campus

S.No.	Description	Qty.	Rate Rs.P.	Unit	Amount Rs.P.
1	Code no.15.56				
	Dismantling old plaster or skirting raking out joints and cleaning the surface for plaster including disposal of rubbish to the dumping ground within 50m lead.	370.00		Sqm	
2	Code no:13.3.1				
	20mm cement plaster of mix 1:4 (1cement : 4 fine sand)	380.00		Sqm	
3	Code no:14.42.1				
	White washing with lime to give an even shade-Old work (two or more coats).	665.00		Sqm	
4	Code no:14.46				
	Removing dry or oil bound distemper, water proofing cement paint and the like by scrapping, sand papering and preparing the surface smooth including necessary repairs to scratches etc. complete.	1150.00		Sqm	
5	Code no:14.45.1				
	Distempering with oil bound washable distemper of approved brand and manufacture to give an even shade - Old work (one or more coats).	1150.00		Sqm	
6	Code no:13.43.1				
	Applying one coat of cement primer of approved brand and manufacture on wall surface - Cement primer	380.00		Sqm	
7	Code no:14.66.1				
	Finishing walls with Acrylic Smooth exterior paint of required shade - Old work (Two or more coats applied @ 1.67 lts/10 sqm.) on existing cement	1250.00		Sqm	

	paint surface			
8	Code no:14.54.1			
	Painting with synthetic enamel paint of approved brand and manufacture of	210.00	Sqm	
	required colour to give an even shade - One or more coats on old work.			
9	Code no:14.6.1			
	Renewing glass panes, with wooden	0.50	Sqm	
	fillets wherever necessary - Float	0.50	Sqiii	
	glass panes of thickness 4mm.			
10	Code no:9.20.1			
	Providing and fixing ISI marked flush	2.10	Sqm	
	door shutters conforming to IS:2202			
	(Part 1) decorative type, core of block			
	board construction with frame of 1 st			
	class hard wood and well matched			
	teak 3 ply veneering with vertical			
	grains or cross bands and face veneers			
	on both faces of shutters. 35mm thick			
	including ISI marked stainless steel butt hinges with necessary screws.			
11	Code no:9.23			
11	Extra for providing lipping with teak	2.10	Sqm	
	wood battens 25mm minimum depth	2.10	Sqiii	
	on all edges of area shutters (over all			
	area of door shutter to be measured)			
	over item no.9.20 and 9.21			
12	Code no:13.50.1			
	Applying priming coat - with ready	5.10	Sqm	
	mixed pink or grey primer of			
	approved brand and manufacture on			
	wood work (hard and soft wood).			
13	Code no:13.61.1			
	Painting with synthetic enamel paint	5.10	Sqm	
	of approved brand and manufacture to			
	give an even shade - Two or more			
	coats on new work.			
14	Code no:9.96.1			
	Providing and fixing aluminium	1.00	Nos	
	sliding door bolts ISI marked			
	anodised (anodic coating not less than			
	grade AC 10 as per IS:1868)			
	transparent or dyed to required colour or shade with nuts and screws etc.			
	complete:- 300x16mm			
<u> </u>	complete. Sookionini			

15	Code no:9.97.1			
	Providing and fixing aluminium tower	1.00	Nos	
	bolts ISI marked anodised (anodic			
	coating not less than grade AC 10 as			
	per IS:1868) transparent or dyed to			
	required colour or shade with			
	necessary screws etc.complete : -			
	300x10mm			
16	Code no:9.100.1			
	Providing and fixing aluminium	2.00	Nos	
	handles ISI marked anodised (anodic			
	coating not less than grade AC 10 as			
	per IS:1868) transparent or dyed to			
	required colour or shade with			
	necessary screws etc.complete :-			
	125mm			
17	Code no:16.100			
17	Acid cleaning for the existing Mosaic	670.00	Sqm	
17	Acid cleaning for the existing Mosaic floors, glazed tiles work and removing	670.00	Sqm	
17	Acid cleaning for the existing Mosaic floors, glazed tiles work and removing the stains and decays to give a glassy	670.00	Sqm	
17	Acid cleaning for the existing Mosaic floors, glazed tiles work and removing the stains and decays to give a glassy look etc complete (The acid used shall	670.00	Sqm	
17	Acid cleaning for the existing Mosaic floors, glazed tiles work and removing the stains and decays to give a glassy look etc complete (The acid used shall be 32% concentrated hydrochloric	670.00	Sqm	
17	Acid cleaning for the existing Mosaic floors, glazed tiles work and removing the stains and decays to give a glassy look etc complete (The acid used shall be 32% concentrated hydrochloric acid after taking on the precautionary	670.00	Sqm	
	Acid cleaning for the existing Mosaic floors, glazed tiles work and removing the stains and decays to give a glassy look etc complete (The acid used shall be 32% concentrated hydrochloric acid after taking on the precautionary measures)	670.00	Sqm	
17	Acid cleaning for the existing Mosaic floors, glazed tiles work and removing the stains and decays to give a glassy look etc complete (The acid used shall be 32% concentrated hydrochloric acid after taking on the precautionary measures) Code no:11.43			
	Acid cleaning for the existing Mosaic floors, glazed tiles work and removing the stains and decays to give a glassy look etc complete (The acid used shall be 32% concentrated hydrochloric acid after taking on the precautionary measures) Code no:11.43 Fixing glazed/Ceramic/vitrified floor	5.00	Sqm	
	Acid cleaning for the existing Mosaic floors, glazed tiles work and removing the stains and decays to give a glassy look etc complete (The acid used shall be 32% concentrated hydrochloric acid after taking on the precautionary measures) Code no:11.43 Fixing glazed/Ceramic/vitrified floor tiles with cement based high polymer			
	Acid cleaning for the existing Mosaic floors, glazed tiles work and removing the stains and decays to give a glassy look etc complete (The acid used shall be 32% concentrated hydrochloric acid after taking on the precautionary measures) Code no:11.43 Fixing glazed/Ceramic/vitrified floor tiles with cement based high polymer modified quick-set tile adhesive			
	Acid cleaning for the existing Mosaic floors, glazed tiles work and removing the stains and decays to give a glassy look etc complete (The acid used shall be 32% concentrated hydrochloric acid after taking on the precautionary measures) Code no:11.43 Fixing glazed/Ceramic/vitrified floor tiles with cement based high polymer modified quick-set tile adhesive (water based) conforming to			
	Acid cleaning for the existing Mosaic floors, glazed tiles work and removing the stains and decays to give a glassy look etc complete (The acid used shall be 32% concentrated hydrochloric acid after taking on the precautionary measures) Code no:11.43 Fixing glazed/Ceramic/vitrified floor tiles with cement based high polymer modified quick-set tile adhesive (water based) conforming to IS:15477, using 5kg adhesive per sqm			
	Acid cleaning for the existing Mosaic floors, glazed tiles work and removing the stains and decays to give a glassy look etc complete (The acid used shall be 32% concentrated hydrochloric acid after taking on the precautionary measures) Code no:11.43 Fixing glazed/Ceramic/vitrified floor tiles with cement based high polymer modified quick-set tile adhesive (water based) conforming to			

I hereby abide by the rules & regulations stipulated in the CPWD form no.6 & 8 $\,$

Contractor

Assistant Engineer