PONDICHERRY UNIVERSITY ENGINEERING WING

SCHEDULE OF WORK

<u>Name of the work:</u> Cleaning of water tanks in the Pondicherry University campus

S. No.	Description	Qty.	Rate Rs.P.	Unit	Amount Rs.P.
	Cleaning of under around sump Over	7850.00	N5.F .	Sam	N5.F .
1.	Cleaning of under ground sump, Over	/850.00		Sqm	
14.78	Head R.C.C. Tank (independent staging)				
11.70	including disposal of slit and rubbish, all				
	as per direction of Engineer-in-Charge.				
	The cleaning shall consist following operations:- (i)Tank shall be emptied of				
	water by pumping & bottom shall be				
	cleaned of silt and other deposits. (ii)				
	Entire surface area of the sump shall then				
	scrubbed thoroughly with wire brush etc.				
	and pressure washed with water. (iii)				
	Chlorination of RCC internal surface by				
	liquid chlorine. (iv) The treated surface				
	shall be dried using air jetting and all				
	loose particles shall be removal from the				
	surface. (v) Finally the surface shall be				
	treated with ultraviolet radiation etc. as				
	per direction of Engineer-in-Charge.				
2.	Cleaning of terrace/loft water storage	127500		Litre	
	tank (inside surface area) upto2000 litre				
14.75A	capacity at all heights with coconut				
	brushes, duster etc., removal of silt,				
	rubbish from the tank and cleaning the				
	tank with freshwater disinfecting with				
	bleaching powder @ 0.5gm per litre				
	capacity of tank including marking the				
	date of cleaning on the side of tank body				
	with the help of stencil and paint and				
	disposing of malba all complete as per				
	direction of Engineer-in-Charge. (The				
	old date already written on tank should				
	be removed with paint remover or black				
	paint and if date is not written with the				
	stencil or old date is not removed				
	deduction will be made @ Rs. 0.10 per				
	litre) (if during cleaning any GI fittings				
	or ball cock is damaged that is to be				

repaired by contractor at his own cost and nothing extra will be paid on this account)		
TOTAL		

* During the above operation of cleaning any GI/PVC/UPVC/ASTM etc. fittings or ball cock is damaged that is to be repaired by contractor at his own cost and nothing extra will be paid on this account.

* Marking the date of cleaning on the side of the tank body with the help of stencil and paint and disposing of malba all complete.(the old date already written on tank should be removed with paint remover or black paint and if date is not written with the stencil or old date is not removed deduction will be made @ Rs.0.10 per litre.

CONTRACTOR

EXECUTIVE ENGINEER